



PEPIN DISTRIBUTING

4121 50th Street



50th STREET



- A - CONTROLS THE OFFICE
- B - CONTROLS THE WAREHOUSE
- C - CONTROLS THE GARAGE & STORAGE
- = HYDRANT
- P = PROPANE
- LB = LOCK BOX
- Y = FD HOOKUP
- E/A = MAIN ELECTRICAL/ ANNUNCIATOR
- GS = GAS PUMP SHUT OFF